





M18SIM Software update Created on: 12/12/2024

The latest software can be downloaded here:

MONITOR UPDATE 3.0.0.75:

https://milwaukee-downloads.s3.eu-west-2.amazonaws.com/MTCam_monitor_RK3568_3_0_0_75.zip

Download, <u>unzip</u> the file, and copy it to a USB-Drive.

Step 1

Open USB Cage:

Step 2

Enter USB-Drive into USB-A port:

⁵ Network of service center managed by a SBU 1/4





¹ No communication outside TTI SBU's and EMEA

² Importers, distributors and service providers in a country (where there is no TTI SBU management) ³ SBU's

⁴ Network of customers who sell our tools in a country, managed by TTI SBU

AFTER SALES SERVICE Service Instruction Sheet Part Number: 4000477334;





Step 3

Step 4

Step 5

Navigate to Settings:

Go to System Update:

Go to Wireless Monitor:





2/4

AFTER SALES SERVICE Service Instruction Sheet Part Number: 4000477334;





Step 6

Step 7

Go to Update File:

Confirm Software Update:

Wireless Monitir is updating (takes 2-5 minutes)







Step 8

3/4









Step 9

Wireless Monitor Restarts after Update is Complete